SERVICE DEPARTMENT BULLETIN

BULLETIN #90291

GENERAL CLASSIFICATION: Game Boy Unit Repair
SPECIFIC SUBJECT: Liquid Crystal Display (LCD) Replacement
UNITS AFFECTED: G02800000 or Lower

All LCDs subject to this notice would, after a period of usage, start showing black and/or missing lines. To resolve this difficulty, the Game Boy front assembly should be replaced under warranty. The repair may only be performed once during the life of the Game Boy.

Under no circumstances is the front assembly to be replaced at no cost to the consumer if the LCD is cracked or shattered. This does not qualify as a manufacturer's defect.

The only part to be replaced under this Service Bulletin is the Game Boy Front Assembly (Part No. 27214). Nintendo will also cover up to $2.00 in miscellaneous parts that are needed to make the Game Boy unit usable. **All units within this serial number range also require a rear housing replacement (part #18406).**

Repair Action

In warranty/Out of warranty - Perform modification and submit warranty claim form to Nintendo. Mark the claim form, "Special warranty" Service Bulletin #90291. No proof of purchase is required.